

FIG.1





FIG.2



A-A SECTION

FIG.3




FIG.4A




FIG.4B




FIG.5




FIG.6




FIG.7




FIG.8




FIG.9




FIG.10




FIG.11A




FIG.11B




FIG.12A





FIG.12B



ENLARGED PORTION D
(SECTION OF PLATE-SHAPED STRUCTURE)




FIG.13




FIG.14

| | | | | |
|----------------------|-----------------|-------------|-------------|-------------|
| Pd CONTENT | 1/3 | 1/6 | 1/12 | 1/24 |
| CORROSION RESISTANCE | HIGH ←————→ LOW | | | |
| (PURITY OF Ag) | approx. 67% | approx. 83% | approx. 92% | approx. 96% |